

Έκθεση συντήρησης και επισκευής

MERCEDES GLC COUPE (PC) (FV461YX)

Mileage	Description	Serviced by	Date
65 204 Χλμ	Guaina proiezione tubi	ASM SERVICE SRL	31/01/2023
65 204 Χλμ	Revisione mctc	ASM SERVICE SRL	31/01/2023
64 594 Χλμ	Filtro aria	ASM SERVICE SRL	26/01/2023
64 594 Χλμ	Filtro carbone attivo riscaldamento/climatizzatore	ASM SERVICE SRL	26/01/2023
64 594 Χλμ	Filtro gasolio	ASM SERVICE SRL	26/01/2023
64 594 Χλμ	Filtro olio	ASM SERVICE SRL	26/01/2023
64 594 Χλμ	Olio motore 5w30	ASM SERVICE SRL	26/01/2023
44 620 Χλμ	71760763 - FILTRO OLIO	AUTOSHOPPING SRL	15/02/2022
44 620 Χλμ	OLIO MOTORE 5W-30 CASTROL M1	AUTOSHOPPING SRL	15/02/2022
44 620 Χλμ	SENSORE PM10	AUTOSHOPPING SRL	15/02/2022
44 620 Χλμ	sost. sensore pm10	AUTOSHOPPING SRL	15/02/2022
44 620 Χλμ	WRZ631 - FILTRO ABITACOLO	AUTOSHOPPING SRL	15/02/2022
44 620 Χλμ	WRZ631 - FILTRO ABITACOLO	AUTOSHOPPING SRL	15/02/2022
27 204 Χλμ	Filtro aria	ASM SERVICE SRL	12/02/2021
27 204 Χλμ	Filtro carbone attivo riscaldamento/climatizzatore	ASM SERVICE SRL	12/02/2021
27 204 Χλμ	Filtro olio	ASM SERVICE SRL	12/02/2021
27 204 Χλμ	Pastiglie freno ant. Pastiglie freno ant. Ts pas	ASM SERVICE SRL	12/02/2021
27 204 Χλμ	Sensore usura freni ant.	ASM SERVICE SRL	12/02/2021
27 204 Χλμ	Serie pastiglie freni post.	ASM SERVICE SRL	12/02/2021
27 204 Χλμ	Sostituzione olio motore (*)	ASM SERVICE SRL	12/02/2021
17 614 Χλμ	36IF002 - FILTRO ARIA	AUTOSHOPPING SRL	26/05/2020
17 614 Χλμ	OLIO MOTORE 5W-30 SYNTH CASTROL (MB.229.31)	AUTOSHOPPING SRL	26/05/2020
17 614 Χλμ	OX153/7D - FILTRO OLIO	AUTOSHOPPING SRL	26/05/2020