

Maintenance History

Generation Date 04/12/2023

Plate Number IYH3120
BO Vehicle Number 1018356
Make MERCEDES Model MERCEDES CITAN 1.5 109 CDI 90HP
Vehicle Description MERCEDES CITAN 1.5 109 CDI 90HP TOURER LONG
Contract Number 5014816

Event date	Mileage	Event description	Supplier name
10/05/2023	123745	Wiperblade front	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
10/05/2023	123745	Pollen filter	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
10/05/2023	123745	Oil filter	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
10/05/2023	123745	Lamps	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
10/05/2023	123745	Air filter	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
01/02/2022	86185	Rear break - pads	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
01/02/2022	86185	Front break - pads	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
01/02/2022	86185	Front break - pads	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Pollen filter	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Pollen filter	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Fuel filter	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Fuel filter	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Brake fluid	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Brake fluid	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Air filter	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	Air filter	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.
26/01/2022	85951	80000 maintenance	Μ.ΙΩΑΝΝΙΔΗΣ Α.Ε.Β.Ε.

07/04/2021	59203	Battery	ΛΑΜΔΑ STAR A.E.
07/04/2021	59203	Battery	ΛΑΜΔΑ STAR A.E.
07/04/2021	59203	Battery	ΛΑΜΔΑ STAR A.E.
07/04/2021	59203	Battery	ΛΑΜΔΑ STAR A.E.
06/07/2020	40866	Pollen filter	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
06/07/2020	40866	Oil filter	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
06/07/2020	40866	BMW - Inspection I	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
06/07/2020	40866	Air filter	Δ. ΑΝΤΩΝΟΠΟΥΛΟΣ Α.Ε.
01/07/2020	40000	Pirelli - Summer	ΕΛΑΣΤΙΚΑ PIRELLI Α.Ε.Ε.

Event date	Mileage	Event description
«TableStart: Maintenance historyBodyR epairGr»«Eve ntDate»	«KM»	«Description» «TableEnd:MaintenancehistoryBody RepairGr»