

Maintenance History

Generation Date 01/12/2023

Plate Number IYZ1455
BO Vehicle Number 1016830
Make NISSAN **Model** NISSAN QASHQAI (O)1.5 DCI ACENTA
Vehicle Description NISSAN QASHQAI (O)1.5 DCI ACENTA (O)1.5 DCI ACENTA
Contract Number 5013716

Event date	Mileage	Event description	Supplier name
14/09/2023	128824	Motortest	AUTOVISION SAKAR A.E.
29/08/2023	128848	Pollen filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
09/05/2023	119631	Clutch - various	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
09/05/2023	119631	Clutch - various	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
10/04/2023	118468	Battery	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
10/04/2023	118468	Battery	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Pollen filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Front break - pads	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Front break - pads	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Brake fluid	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
26/07/2022	99703	Air filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
16/02/2022	84389	Clutch - various	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
16/02/2022	84389	Clutch - various	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
16/02/2022	84389	Brake fluid	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
16/02/2022	84389	Brake fluid	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
23/11/2021	80345	Pirelli - Summer	ΕΛΑΣΤΙΚΑ PIRELLI Α.Ε.Ε.
02/09/2021	73543	Pollen filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
02/09/2021	73543	Pollen filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
02/09/2021	73543	Oil filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.

02/09/2021	73543	Oil filler cap	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
02/09/2021	73543	Motortest	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
02/09/2021	73543	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
02/09/2021	73543	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
08/10/2020	54126	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
08/10/2020	54126	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Pollen filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Oil filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Front break - pads	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53233	Front break - pads	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Engine - general	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Brake fluid	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2020	53223	Air filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
07/09/2020	51201	Motortest	AUTOVISION SAKAR A.E.
16/03/2020	39845	Pirelli - Summer	ΕΛΑΣΤΙΚΑ PIRELLI A.E.E.
29/09/2019	27945	Motortest	AUTOVISION SAKAR A.E.
24/09/2019	27945	Pollen filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2019	27945	Oil filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2019	27945	Fuel filter	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2019	27945	30000 maintenance	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
24/09/2019	27945	30000 maintenance	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.
27/03/2019	13679	Oil level check	ΛΑΪΟΝ ΕΛΛΑΣ Α.Ε.

Event date	Mileage	Event description
10/13/2021 12:00:00 AM	77581	BodyRepair
10/13/2021 12:00:00 AM	77581	BodyRepair

10/13/2021 12:00:00 AM	77581	BodyRepair
10/13/2021 12:00:00 AM	77581	BodyRepair
10/13/2021 12:00:00 AM	77581	BodyRepair
10/13/2021 12:00:00 AM	77581	BodyRepair